

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

KZ1503
NW
> 1
1.890 mi.
9980 ft.

APPROVED OIL
20TH AVE/ BATH AVE
BROOKLYN, NY

NY Spills S108764935
N/A

Site 1 of 3 in cluster KZ

Relative:
Higher

Actual:
0 ft.

SPILLS:

Name: APPROVED OIL
Address: 20TH AVE/ BATH AVE
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0707173 / 2007-10-01
Facility ID: 0707173
Facility Type: ER
DER Facility ID: 337301
Site ID: 387814
DEC Region: 2
Spill Cause: Equipment Failure
Spill Class: C3
SWIS: 2401
Spill Date: 2007-09-28
Investigator: RMPIPER
Referred To: Not reported
Reported to Dept: 2007-09-28
CID: 404
Water Affected: Not reported
Spill Source: Commercial Vehicle
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2007-09-28
Spill Record Last Update: 2009-09-14
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: Not reported
DEC Memo: "DEC Piper responded to site. Due to equipment failure, approx 300 gal of oil was spilled t oroadway. FDNY, OEM, DEP, DSNY on scene TO sand and sweep road. Miller ENv Group responded to clean up remaining oil. Road closed to 1200. Approx 20 gal enterend storm drain. MEG vacced pools of oil on side of road and storm drain. Spread speedy dry down upon completion of work."
Remarks: "fire departments are on scene; batalon 42 is on scene can contact him for anymore information"

All Materials:

Site ID: 387814
Operable Unit ID: 1145014
Operable Unit: 01
Material ID: 2135332
Material Code: 0015
Material Name: motor oil
Case No.: Not reported
Material FA: Petroleum
Quantity: 100.00
Units: G

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Recovered: .00
Oxygenate: Not reported